



AFRICAN ADVANCED LEVEL TELECOMMUNICATIONS INSTITUTE (AFRALTI)

## COURSE OUTLINE

**Title:** CERTIFIED FIBER OPTIC SPECIALIST, TESTING (CFOS/T) COURSE

**Duration:** 5 days

### Part One: Fiber Optics Testing Lectures

#### Course Outline:

#### Part One: Theoretical Training

Day	Main Topics	Sub Topics Lectures
Day One	<p>Lecture 1: Fiber Optics Testing Overview.</p> <p><b>Lecture 2: Fiber Test Instruments Overview</b></p>	<ol style="list-style-type: none"> <li>1. Fiber Optics testing presentation <ul style="list-style-type: none"> <li>• Mechanical tests</li> <li>• Geometrical tests</li> <li>• Transmission tests</li> <li>• Optical tests</li> <li>• Performance tests</li> <li>• Environmental tests</li> </ul> </li>   <li>2. Familiarization with Instruments for Fiber Testing: <ul style="list-style-type: none"> <li>• Fiber Tracer</li> <li>• Visual Fault locator</li> <li>• Optical microscope</li> <li>• Light Source</li> <li>• Power meter</li> <li>• Optical time Domain Reflectometer (OTDR)</li> <li>• Optical return loss meter</li> <li>• Spectrum Analyzer</li> <li>• Polarization Mode Analyzer</li> <li>• CD Analyzer</li> <li>• Bit Error Rate tester</li> <li>• Protocol Analyzer</li> </ul> </li>   <li>3. Fiber Test Parameters</li> </ol>

	<b>Lecture 3: Fiber Impairments and test Parameters</b>	<ul style="list-style-type: none"> <li>• Continuity testing</li> <li>• Polarity testing</li> <li>• Visual tracing</li> <li>• Visual fault location</li> <li>• Splice verification</li> <li>• Connectors quality inspection</li> <li>• Connectors cleaning</li> <li>• Fiber identification</li> <li>• Power tests</li> <li>• Attenuation</li> <li>• Insertion loss tests</li> <li>• PMD Dispersion test</li> </ul>
Day Two	<b>Lecture 1: Fiber Safety:</b>	<p><b>(a) General Fiber Safety Rules</b> Eye Safety and mandatory wearing of safety glasses</p> <ul style="list-style-type: none"> <li>• Invisible Laser Power</li> <li>• High power DWDM systems</li> <li>• Bare fibers and scraps</li> <li>• Safe disposal of fiber scraps</li> <li>• Working with chemicals, adhesives, Alcohol and flammable materials</li> <li>• Observance of MSDS</li> <li>• Working with sharp fiber tools, Arc welders fusion splicer,</li> <li>• Eating , drinking and smoking in FO lab</li> </ul> <p><b>(b) Construction safety Rules</b></p> <ul style="list-style-type: none"> <li>• safety glasses and dust coats</li> <li>• Safety boots, safety jackets, safety helmets with reflectors</li> <li>• fiber scraps and Fresnel</li> <li>• Dispose of fiber scraps safely</li> <li>• Only splice in a well-ventilated room</li> <li>• cleanliness- fiber has zero tolerance to dust</li> <li>• Bonding and grounding of metallic cables</li> <li>• Fire stopping</li> </ul>
Day Two	<b>Lecture 2: Fiber Optics Safety &amp; Standards</b>	<p><b>Familiarization with Fiber Safety standards</b></p> <ul style="list-style-type: none"> <li>• TIA Standards TIA 568, ISO 11801,</li> <li>• ITU Standards: G.652, G 653, G.654, G.655, G. 657</li> <li>• NECA/FOA 301-2016 Installation and Testing Standard for Fiber Optics (American)- A Soft copy shall be provided to trainees</li> <li>• Safety Poster</li> </ul>

**Part Two:**

**Hands on Training Syllabus**

Day	Lab No	Task	Test Instruments	Training Activities
Day Three	1	<b>Connector Inspection with Microscope</b> a	<ol style="list-style-type: none"> <li>1. Optical microscope</li> <li>2. Patch cords with connectors at end</li> </ol>	<ul style="list-style-type: none"> <li>• Inspect several connectors on patch cords and pig tails with microscope</li> <li>• Look for scratches, dirt, breaks, dust, polishing defects</li> <li>• Clean a dirty connector</li> </ul>

				<ul style="list-style-type: none"> <li>Evaluate performance of the clean connector</li> </ul>
Day Three	2	<b>Visual Fault Location</b>	<ol style="list-style-type: none"> <li>Visual Fault Locator (Laser)</li> <li>Tracer (LED)</li> <li>Patch cords of 2 meters</li> <li>Cable of 10 meters</li> <li>PC and APC Connectors</li> </ol>	<ul style="list-style-type: none"> <li>Locate breaks in a fiber</li> <li>Locate stress points on a fiber</li> <li>Locate fiber bends</li> <li>Identify high loss connectors</li> <li>Identify splices</li> <li>Identify fiber polarity on zip cord cables</li> </ul>
Day Three	3	<b>Optical Power measurements</b>	<ol style="list-style-type: none"> <li>Light Source</li> <li>Power meter</li> <li>Low loss Reference cables</li> <li>Low loss Connectors</li> <li>Patch cords</li> <li>Cable to test.</li> </ol>	<ul style="list-style-type: none"> <li>Transmit known optical power through a fiber (dBm) light source</li> <li>Measure received power with power meter (dBm)</li> <li>Calculate power loss (dB)</li> <li>Compare with receiver sensitivity</li> <li>Calculate loss margin</li> <li>Document Results</li> </ul>
Day Three	4	<b>Using Optical Power Meter</b>	<ol style="list-style-type: none"> <li>Power Meter</li> <li>Light Source</li> </ol>	<ul style="list-style-type: none"> <li>Connect a source to a meter with an appropriate patch cable.</li> <li>Set same wavelength on light source and power meter</li> <li>Set the meter's calibration to the wavelength of the source.</li> <li>Using the meter's dBm scale, measure the power in dBm.</li> <li>convert that power to Watts.</li> </ul>
Day Four	5	<b>Link Power budget Analysis</b>	<ol style="list-style-type: none"> <li>Electronics calculator</li> </ol>	<p>Link Budget Analysis Exercises for:</p> <ol style="list-style-type: none"> <li>Multimode campus LAN backbone.</li> <li>Multimode LAN link at 10G,</li> <li>Single mode long haul network,</li> <li>Single mode metro network link, 1310nm.</li> </ol>
Day Four	6	<b>Insertion Loss testing</b>	<ol style="list-style-type: none"> <li>Power meter</li> <li>Light Source</li> <li>Cable to test-</li> <li>Launch reference cable-</li> <li>Receive reference cable at least 500 meters</li> <li>Mating Adapters</li> <li>Fiber Tools Kit</li> </ol>	<ul style="list-style-type: none"> <li>Single ended patch cord test method (FOTP-171)</li> <li>Double ended loss test of a simulated cable plant ((OFSTP-14) and (OFSTP-7)</li> <li>3 cable reference test method (OFSTP-14) method C, TIA 568-C</li> <li>Set zero dB reference levels</li> <li>Measure receiver power</li> <li>Measure connectors loss on both ends</li> <li>Measure cable plant loss</li> </ul>

				<ul style="list-style-type: none"> <li>• Compare loss results with calculated Loss Budget</li> <li>• Calculate insertion losses for single, double and 3 cable test methods</li> <li>• Record results</li> </ul>
Day Four	7	<b>OTDR Testing</b>	<ol style="list-style-type: none"> <li>1. OTDR</li> <li>2. Launch and receive cables (1 kilometer) pulse suppressor</li> <li>3. Patch cords</li> <li>4. Pig tails</li> <li>5. Long single mode cable ( 1,000 meters or more)</li> <li>6. Fiber Tools kit</li> </ol>	<ul style="list-style-type: none"> <li>• Measure length of launch cable</li> <li>• Make OTDR trace at 1310nm and 1550 nm</li> <li>• Identify fiber cuts, stresses, bends</li> <li>• Identify initial pulse</li> <li>• Identify dead zone</li> <li>• Measure connector loss, reflectance</li> <li>• Identify cable end</li> <li>• Identify Noise</li> <li>• Measure fiber length with OTDR</li> <li>• Measure cable plant loss end to end with OTDR</li> <li>• Measure fiber attenuation</li> <li>• Compare traces at 1310 nm and 1550 nm/1625 nm</li> <li>• Document Results</li> <li>• Interpret OTDR Test Results</li> </ul>
Day Five	8	<b>Fusion Splicing and OTDR testing and link trouble shooting</b>	<ol style="list-style-type: none"> <li>3. Fusion Splicer</li> <li>4. Cleaver</li> <li>5. Fiber stripper</li> <li>6. Cable cutter</li> <li>7. Single mode cable</li> <li>8. OTDR</li> <li>9. Pig tails</li> <li>10. Fiber Tools kit</li> </ol>	<ul style="list-style-type: none"> <li>• Strip and cleave two fibers</li> <li>• Splice two fibers</li> <li>• Measure splice attenuation</li> <li>• Make OTDR Trace</li> <li>• Measure cable plant Loss with OTDR</li> <li>• Measure splice loss with OTDR</li> <li>• Compare with Fusion splicer loss figure</li> <li>• Record Results &amp; Interpret results</li> </ul>
	9	<b>Revision Exercises</b>	Revise past examinations papers and do online tests	<ul style="list-style-type: none"> <li>• Online tests</li> </ul>
	10	<b>Examination</b>	Examination CFOS/T	<ul style="list-style-type: none"> <li>• Written Examination</li> </ul>

**Administering of Test: Written CFOT Test (approx. 2 hours)**

## Reference materials

Textbook: Fiber Optics Reference Guide by Jim Hayes, Supplementary Study Materials includes Workbook and Lab Manual.

AFRALTI CFOT, CPCT, CFOS/D, CFOS/H FOA Approved School # 758

<http://foa-approved.org/schools/african-advanced-level-telecommunications-institute-afralti>

For more information, please contact us on:

**Tel: +254 710 207 061, +254 733 444 421**

[\*\*training@afralti.org\*\*](mailto:training@afralti.org)

[\*\*www.afralti.org\*\*](http://www.afralti.org)